



RECEIVED

TO: Land Division Fil

EPA Region 5 Records Ctr.

APR 21 1980

DATE: April 8, 1980FROM: G.E. Steele

368295

E.P.A. — D.L.P.C.

☒ Information only

STATE OF ILLINOIS

SUBJECT: Mason Co. LPT # 11580408 Decatur/Mason Co. #2☐ Response requested

None of this sites special wastes were considered as hazardous. With their notification letters, they received a large number of letters for the Davis Junction site. They also received a letter on a permit that was expired.

A heavy wind, blowing toward the north was creating quite a problem with blowing litter. Most of this litter was being caught by perimeter fences. Large amounts of wind blown litter were observed ^{off} of the site to the south and east.

The Active area was located in the central part of the site. North of the active area was an approximate 10 yard by 15 yard section ~~to~~ were refuse was seen protruding through cover. South of the active area was an approximate 10 yard by 10 yard area in a similar condition.

A small ditch ~~to~~ has been dug through the south perimeter berm. This was to allow ~~the~~ runoff water contained west of the drain tile to escape before ~~the~~ the area filled and flowed over into refuse. The water level was nearly at the top of the berm and tile ridge. This water had not come in contact with refuse. The berm had been opened earlier in the day, and dirt was present to close it off that evening.